<b>Work Ordo</b> <i>July 19, 2010 1</i>	er ID 60688 · 2:38:23 PM				P	{ELI	MINA	ARYI	SSUE	Page 1
Item ID: Revision ID: Item Name:	D4101-041 Pre-flight Step Ass'y		Accept				S	etup Sta Sto		
Start Date: Required Date: Reference:	20/07/2010 Start Qty: 1.00 21/07/2010 Req'd Qty: 1.00			Cust Item I Customer:	D:	POSITIVE	)	Sto		<b>1</b> 11 <b>1</b> 181 1181 1 <b>18</b> 1
Approvals:	Process Plan:	Date:	Tooling: SPC (Y/N):		ate: ate:		N	tun Sta Sto	1.15-11161.61	
Sequence ID/ Work Center I Draw Nbr	Operation Description Revision Nbr		Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
DY60/	DAY		0.00				$\overline{\mathcal{M}}$			
Small Fab Small Fab	Memo 1 - Assemble a	us per dwg	0.00	A 10/07/2	۵					
QC Quality Control	QC5- Inspect part complete	eness to step on W/O	0.00 - May 5	heeto to PAY my only wolveto ky						·
120 Packaging Packaging	Identify as per dwg & Stoc Memo	k Location: The	0.00	Joseph 10-07.	2/					

Work Order I	D 60688	Ş
--------------	---------	---



Page 2

July 19, 2010 12:38:24 PM

**Required Date:** 21/07/2010

Item ID:

D4101-041

QC:

Accept



Setup Start

Stop



**Revision ID:** 

Item Name: **Start Date:** 

Pre-flight Step Ass'y

20/07/2010

Start Oty: 1.00

Req'd Qty: 1.00



Date:

**Cust Item ID:** 

**Customer:** 

Reference:

Approvals:

Process Plan:

Operation

Description

QC21- Final Inspection - Work Order Release

**Tooling:** Date:

Date:

Date:

Run Start

Stop



Sequence ID/

**Work Center ID** 

130

Memo

0.00

SPC (Y/N):

Set Up/

Run Hours

Tool ID

Tool # Plan Code

Accept Qty

Reject Reject Qty

Insp. Number Stamp

Quality Control

0.00

10.01.3 POSITIVE RECALL

RELEASED

MG-7-21

July 19, 2010 12:38:23 PM

Work Order ID: 60688

Parent Item:

D4101-041

Parent Item Name: Pre-flight Step Ass'y



**Start Date: 20/07/2010** 

**Required Date: 21/07/2010** 

Start Qty: 1.00

Required Qty: 1.00

Comments:

IPP Rev:A 10.07.07 new issue DD verf:JLM

	Replacement tem ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
AN310-4		Purchased	No			100	Each	53.0000		1			
NUT				Location		Loc	Qty	Loc Code				1	1
				ST324			53		-		Sp	0	07/2
					114716		3		_		_ 30	, , (	ı
AN4-22		Purchased	No		115107	100	50 Each	10.0000	1 -	1			
		Purchased	140			100	Enteri	10.0000		1			
									! ! <b>! ! ! ! ! !</b> !	~			<del></del>
				Location		Loc	<u>Qty</u>	Loc Code					407/
				ST359			10				-	77	4071
					115156		10		_			CO	19
D4101-1	I	Manufactured	No			100	Each	0.0000	1   [[[]]   []]	1			
							66 59	0					
Bracket D4101-3		Manufactured	No			100	Each	0.0000	1	1		1	2/76
	1	Manufactured	140				B 604			1	Sh	colo	5 + 1 K
Step				•			<i>P</i> - C (		1 18611 1861				
D4101-5		Manufactured	No			100	Each	0.0000	1	1			,
						B	6059	) (a)			$\bigcirc$ a	(8)0	2 /2
Spring	•							23			<del>- 20</del>	(0,0	<del></del>
MS24665-136		Purchased	No			100	Each	157.0000	1	1			
												<u>.</u>	
Cotter Pins													
		•		Location		Loc	<del></del>	Loc Code				)	1
				ST309	2421		157 .157		_	- 4	- SB-	101	07/2

July 19, 2010 12:38:23 PM

Work Order ID: 60688

Parent Item:

D4101-041

Parent Item Name: Pre-flight Step Ass'y



Start Date: 20/07/2010

Required Date: 21/07/2010

Start Qty: 1.00

Required Qty: 1.00

NAS1149D0416J

Purchased

No

No

100

Each

513.0000

Washer

Location	Loc Qty	Loc Code			
ST298	513				
110153	2				1 100
114103	50				10/07/20
114884	200			$\geq 1$	<i>t</i> 1
115107	200			_	
13910	61		_2_		
	100 Each	3,431.000	2		

Purchased NAS1149D0463J

Washer

Location	Loc Qty
ST297	3335
115000	3335
ST298	96
10096	10
114576	68
114883	18


Loc Code

\_\_\_\_ So 10/07/20

w/0 0400 60688



ITEM	QTY -041	PART NUMBER	DESCRIPTION				
	X D4101-041		PRE-FLIGHT STEP ASSEMBLY				
2	1	D4101-3	STEP				
3	1	D4101-5	SPRING				
4	1	AN4-22	BOLT				
5	2	NAS1149D0463J	WASHER				
6	2	NAS1149D0416J	WASHER				
7	1	MS24665-136	COTTER PIN				
8	1	AN310-4	NUT				
9	1	D4101-1	BRACKET				



## **PRELIMINARY ISSUE**

**₽** 10.07.12

AN310-4 WAS AN310 (ZN D3-1); REVISE NOTE MATERIAL (ZN AB-5); 0.850 WAS 0.670 & R0.13 WAS R0.06 (ZN C5-3 & B4-3) 10.07.07 RE-DESIGN D4101-1 (ZN A4-2); R0.16 WAS R0.08 (ZN B3-5) 10.06.02 REVISE PART LIST (ZN D3-1); REMOVE PRIME PAINT (ZN A8-2, A8-4); ADD MATERIAL SPEC TO D4101-5 (ZN A8-5) • 10.05.17 RF PA1 NEW ISSUE RF 10.05.06 REV. DESCRIPTION DATE

DESIGN	RF	DART AERO	SPACE LTD		
DRAWN	RF	HAWKESBURY, ONTARIO, CANADA			
CHECKED		DRAWING NO.	REV. PA4		
MFG. APPR.		D4101	SHEET 1 OF 5		
APPROVED		TITLE	SCALE		
DE APPR.		PRE-FLIGHT STE			
DATE 10.07.12		COPYRIGHT © 2010 BY DART AEROSPACE LTD THE DROUGH HE PRINCE AND USE THE COPERS CONTINUED THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR DOPE OR COMMENTANTED TO ANY OTHER PERSON WITHOUT			

## D4101-041 PRE-FLIGHT STEP ASSEMBLY

NOTES:
1) MATERIAL: N/A
2) FINISH: NONE
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: NONE
2) INFERIENCATION: IDENTIFY WITH DART P/N "DA101.041" I ISING FI

6) IDENTIFICATION: IDENTIFY WITH DART P/N "D4101-041" USING FINE POINT PERMANENT INK MARKER 7) WEIGHT: 1.19 lbs

8) INSTALL NAS1149D0416J WASHER IN BETWEEN STEP AND BRACKET MATING FACES